



Pos	CPN	Qty	Description
1	HDD1-22-235	1	Pancar rear axle 2022
2	DG2	1	Hex coupler
3	HW036	2	M3 - Cone Set Screw - see Repair kit
4	DGD-020-L-A	1	Ring Gear 1
5	DGD023	2	Bearing 1/4 x 3/8 x 1/8
6	DGD-001-###	1	Spur Gear
7	DGD-020-L-B	1	Ring Gear - Light version
8	T1-2022-235	1	Left Hub Gear Diff 2022
9	FX0043A	1	Fenix Thrust Bearing
14	DGD006	4	satellite
15	FX14-38	1	Ball Bearing Flanged 3/8"x1/4"
16*	T2	1	Belleville holder - see Repair kit
17*	FD12-4	3	Diff Spring - see Repair kit
18*	HW006	1	Self locking nut M4 - standard

Repair kit: DGD022-Mk2

FENIX GEAR DIFF
235mm PANCAR - MK2